



Certificate of Compliance

Certificate Number: 0103-09-16-IIP-GM

MONITORING AUDIT (Full certificate) for the recycling plant:

CENTRO PLASTICA SRL Via Galileo Galilei 10 30035 Mirano (VE), ITALY
--

Process	Input material	Presentation	Equipment capacity (t/a)	Post-consumer material accepted for recycling in previous 12 months (t)*	Output of recycling process	Average post-consumer recycled content of polymer / product (%)	Average pre and post-consumer recycled content of polymer / product (%)	Level of traceability (1 to 2)	Washed material
HDPE recycling	Post consumer bottles (rigid, coloured, clear)	Bales	2.760	2.752,56	HDPE flakes, HDPE granules	100	N.A.	1	yes

Audited by: Giordano Marini	
Date of audit: 09/09/2015	
Period of evaluation: from 01.09.2014 to 31.08.2015	
Period of validity: 25/09/2015 - 24/09/2016	

The recycling process and associated management systems of the aforementioned company for the waste plastic and site shown has been audited and have met the required standards for certification under the EuCertPlast Scheme for European Plastic Recyclers.

This plant is the last recipient of plastics waste and produces products.

Giordano Marini
Via Velleia 2
20900 - Monza

Eucertplast c/o EuPR]
Avenue de Corthenberg 71
B-1000 Brussels

www.eucertplast.eu